

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

165  
202

3700  
1-10

1/10

20T220" 3E26200T




FIG. 1

2/10

10079738.022102




Fig 2

3/10




FIG. 3

10079738.022102



5/10




Fig 5

10079738.022102

10079738.022102




FIG 6A

7/10

1007973B.022102





Fig. 6B



8/10

10079738.022102



9/10

70




Fig. 8

10079738.022102

10/10

DRIVER CONTROL 116  
INPUTS




Fig. 10




Fig. 9

10079738-022102